# DL76 DATA LOGGER SYSTEM INSTRUCTIONS

## **DL76**

# DATA LOGGER SYSTEM INSTRUCTIONS








The DL76 is a battery-powered data logger that can be used with any SeaMetrics flowmeter. It stores pulses for up to 3 years, depending on the user-selected frequency of reading. Indicator lights on the unit flash to indicate when it is functioning and when the battery is low.

The DL76 can be factory-mounted on the meter or remotely mounted. Housings are rugged cast aluminum, gasketed for environmental protection.

When a DL76 logger is placed into operation, it is easily set up using a laptop computer. Data is also retrieved from the DL76 by means of a laptop and can be analyzed on the laptop or easily loaded on a desktop computer for analysis.

FlowInspector software (ordered separately) is required for the downloading, storing, viewing, graphing, charting and printing of data in several formats. FlowInspector requires a PC with Windows 98, NT, 2000, XP, or Vista; CD-Rom drive; 800 x 600 screen resolution; serial port or USB/serial adapter; and a SeaMetrics DC3 data cable. FlowInspector comes in versions compatible with up to 4, up to 16, or 17+ dataloggers.

### **FEATURES**



### **SPECIFICATIONS\***

Power		3.6 Vdc lithium ba	3.6 Vdc lithium battery (included)		
Battery Life		~3 years (varies with sampling interval)			
Temperature		0° to 130° F (-18° to 54°C)			
Rate Units	Volume		mL, liter, gallon, Imperial gallon, cubic foot, cubic meter, million gallon		
	Time	Seconds, minutes, hours, days			
Total Units		, , , ,	Liter, gallon, Imperial gallon, cubic foot, cubic meter, million gallon, acre-foot, acre-inch, megaliter, thousand-gallon		
Data Storage Capacity		Capacity	at	Sampling Interval	
		11 days	at	15 seconds	
		22 days	at	30 seconds	
		44 days	at	60 seconds	
		6 months	at	240 seconds	
		1 year	at	480 seconds	
		3 years	at	1450 seconds	
Indicators		Low battery; Power/flow			
Memory Wraparou	ınd	Selectable options (Stop or Overwrite)			
Clock Accuracy	10 minutes/month	minutes/month (.02%)			

<sup>\*</sup>Specifications subject to change • Please consult our website for current data (www.seametrics.com).

### **MOUNTING**

There are three mounting configurations for a DL76: Mechanical Meter (DL76M), Insertion Magmeter (DL76ME), and Wall (DL76W). The meter mount models match up to any SeaMetrics lower square housing. All configurations can be factory-ordered or field-installed. Converting from one mounting configuration to another requires use of MK10 or MK20 mounting kits.


**Meter Mounting.** Remove the four screws on the meter cover with a 5/32" Allen wrench. After connecting the leads to their respective terminals (see diagram), put the DL76 in place of the meter cover and tighten the screws evenly. The gasket on the DL76 should be visibly compressed by tightening all around.


### **OPERATION**

SeaMetrics FlowInspector V.2 software is required for operation of the DL76. Please consult your FlowInspector manual for instructions in loading the software onto your


computer, setting up your DL76 for use, downloading, storing, and analyzing your data.

### **DIMENSIONS**







### **CONNECTIONS** (see also next page)




### **DL76 TO MECHANICAL METER**



### **DL76 TO MAGMETER**




### **DL76 TO FT415**



0

O

**Caution:** Do not apply external power to the DL76.



### **TROUBLESHOOTING**

Problem	Probable Cause	Try
Laptop screen reads "No connection" and "Active" light is NOT	DL76 is transmitting data. Wait two minutes before taking action.	Wait for "Active" light to blink
blinking	Dead battery in DL76	Replace battery
Laptop screen reads	Loose cable	Tighten cable
"No connection," but "Active" light <u>IS</u> blinking	Bad cable	Test cable (tech bulletin "DL75/76: Testing the DC3 Cable" on Downloads page at www.seametrics.com)
Flow rate incorrect	K-factor setting is incorrect	Make sure K-factor in DL76 matches flow sensor
No flow rate	Damaged flow sensor	Mechanical: See if rotor spins freely EX Magmeter: See if "Status LED" indicator is blinking
	Broken wire	Check for flow rate

**⊘** 

**+**∅

0

► To Flow Sensor

